

STS-97 IFA CABLE INVESTIGATION

Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

Current Status (cont.)

- Additional screens implemented on STS-98 mission
 - X-ray ETAR WTR ordnance cables on both SRBs
 - Electrically test ETAR WTR ordnance cables on both SRBs
 - Cable matrix assembled to evaluate other SRB cables
 - Evaluation performed using type of cable, criticality, lifecycle processing and handling, and historical nonconformance data
 - Identified Forward Separation Bolt Ordnance cables with prior non-conformance history of shield damage
 - Added these cables to x-ray inspection
- Based on x-ray results, two cables removed and replaced
- Electrical tests identified damaged shield on LH ETAR WTR ordnance cable, lower strut system "B"
 - Cable re-terminated with new connector
 - Repaired cable successfully passed electrical tests



STS-97 IFA CABLE INVESTIGATION

Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

Current Status (cont.)

- Previously flown RSRM ignition cables verified acceptable by inspection or test
- Cable sampling plan developed to gain additional insight into condition of all types of SRB cables
 - Engineering assessment selected 100 cables in 13 families based on construction/configuration
 - X-rayed all 100 cables selected
 - No similarities to STS-97 IFA cable found during inspection



SRB CABLE INVESTIGATION

Presenter:
Robert Wright
Organization/Date:
USA-SRB/1-15-01

Problem

- During x-ray inspection of 100 cable sample for STS-97 IFA investigation a break was identified in one conductor of Forward tunnel cable, S/N 1000018
 - Cable provides “C” bus power to forward IEA
 - 6 conductor watertight reusable cable
 - One twisted pair of spare wires
 - One twisted quad for supply and return, redundant
 - Break verified in continuity test while flexing cable





SRB CABLE INVESTIGATION

Presenter:
Robert Wright

Organization/Date:
USA-SRB/1-15-01

Problem (cont.)

- Failure analysis showed
 - No shield damage
 - Break occurred at a “kink” in spare wire at the connector mold to polyurethane jacket transition



Forward Tunnel Cable
(showing wire break magnified)

SRB CABLE INVESTIGATION


Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

WO# 01-004-05D-21
P/N 10400-0050-501
S/N 1000018
X21W5RP2



USA
SRB PHOTO

STS-98



SRB-18

USA
United Space Alliance

SRB CABLE INVESTIGATION

Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

Current Status (cont.)

- No broken strands found in other five conductors
- No chemical or thermal damage noted
- Microscopic evidence indicated this was not a recent failure, fracture surfaces exhibited wear
- Based on failure found on 1000018 cable, team requested additional testing of WTR cables
 - Statistically significant sample size calculated based on population of 700 WTR cables
 - Selected additional 123 cables from inventory
 - 23 were additional databus cable assemblies
 - Team requested wiggle test and x-ray of STS-102 system tunnel cables
 - 36 of 38 cables available for inspection
- Electrical bench flex test developed to evaluate conductor continuity of cables in SRB inventory



SRB CABLE INVESTIGATION

Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

Current Status (cont.)

- Cable sample summary
 - 223 cables x-rayed and bench flex tested
 - 36 cables x-rayed and wiggle tested (on vehicle STS-102)
 - 259 total cables tested
 - 183 of 223 are WTR
 - 194 of 259 are systems tunnel WTR



| | |
|------------------------------------|---------------------------------------|
| SRB CABLE INVESTIGATION | Presenter: Robert Wright |
| | Organization/Date: USA-SRB/1-15-01 |

Current Status (cont.)

- X-ray inspection:
 - One broken conductor found (1000018)
 - Minor to moderate shield damage found on some cables - nothing similar to STS-97 IFA cable
- Bench flex test:
 - Three cables found with a broken conductor
- All four cables were system tunnel WTR cables
- Three of four failures were at aft IEA interface
- Three of four failures were in spare wires (not tested after installation)



| | |
|------------------------------------|--|
| SRB CABLE INVESTIGATION | Presenter: |
| | Robert Wright |
| | Organization/Date: USA-SRB/1-15-01 |

Systems Tunnel WTR Cables Test Summary

| | # cables | # connectors | # conductors | # conductor locations |
|--|-------------|--------------|--------------|--------------------------|
| <i>Inventory (14 Flight sets)</i> | 532 | 1064 | 9240 | 18480 |
| <i>Bench Testing</i> | | | | |
| 1 st "100" cables | 35 | 70 | 2372 | 4744 |
| "123" cables | 123 | 246 | | |
| <i>Totals</i> | 158 | 316 | | |
| <i>On Vehicle Testing</i> | | | | |
| STS-102 | 36 | 72 | 656 | 1312 |
| Total tested | 194 | 388 | 3028 | 6056 |
| (% of inventory) | (36%) | (36%) | (33%) | (33%) |
| Total failed | 4 | 4 | 4 | 4 |
| (% of tested) | (2.06%) | (1.03%) | (0.132%) | (0.066%) |
| % passed | 97.94% | 98.97% | 99.868% | 99.934% |

STS-98



SRB-22



SRB CABLE INVESTIGATION

Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

Statistical Risk Assessment

- Assumptions
 - Conductor wire failures caused by random events
 - Higher number of missions results in higher chance of finding conductor failure
 - Due to number of exposures to random event, not cycle fatigue
 - No process shift or common cause
- Analytical approach
 - Calculated using data at conductor level from 194 system tunnel cables
 - 3028 conductors, at two locations each
 - Four failures found
- Reliability calculations
 - Conductor demonstrated reliability calculated using conductor data
 - Use conductor demonstrated reliability to calculate system (vehicle) reliability



SRB CABLE INVESTIGATION

Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

Statistical Risk Assessment (cont.)

- Account for series (supply & return) and parallel (redundant) arrangement
- Reliability Results
 - Based on four failures found: Flight risk is less than 1 in 7,200
 - Equivalent to a reliability of 0.99986



STS-98 FLIGHT RATIONALE

Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

STS-98 ETAR WTR Ordnance Cable Rationale for Flight

- Cable experience shows shield damage occurs prior to damage of conductors
- X-rays of all ETAR WTR ordnance cables show no evidence of damage similar to STS-97 IFA
 - Cables with suspect shield damage were repaired or replaced
- All ETAR WTR ordnance successfully passed electrical tests cables after final installation
- No evidence of gross handling damage observed in any inspections initiated by STS-97 IFA
- All critical measurements and functions are redundant by design



STS-98 FLIGHT RATIONALE

Presenter:

Robert Wright

Organization/Date:

USA-SRB/1-15-01

STS-98 System Tunnel Cables Rationale for Flight

- Demonstrated reliability shows zero in-flight failures during 101 missions
 - Statistical risk assessment shows demonstrated reliability of 0.99986
- All critical measurements and functions are redundant by design
 - In addition, power circuits have redundancy within each cable
- All other cables, non-WTR, evaluated through testing and non-conformance history, were found acceptable

Team recommendations are mixed regarding flight readiness

